



屯門醫院 手術室大樓擴建計劃通訊

高空工作要留神 落實不同措施 確保工程安全

隨著屯門醫院手術室大樓擴建計劃的地庫工程接近完工，建築團隊開始著手興建大樓主體，並為此作出準備，確保工程持續和安全地推展。

新大樓共設有兩層地庫，地庫結構工程最近已完成，並開展間牆及機電設備安裝。由於下一階段將會進行地面以上的結構工程，為確保安全，以免有物料從高處跌下而造成危險，承建商將會在建築外牆周邊圍上不易燃兼有隔音功能的帆布，作為保護措施。相比起以往建築地盤使用的圍網，這些帆布的保護功效更高。與此同時，工地內的機器將會重新擺位，盡量安放在遠離病房和現有大樓的位置，希望將工程期間造成的滋擾進一步減少。

興建有蓋行人道 方便出入

除了落實上述措施之外，為了確保公眾、醫院職員和工友途經工地一帶時的安全，工地外圍剛於十一月底興建了臨時有蓋行人道，以提供一個安全、放心的路面環境。這條有蓋行人道符合現行條例規定，闊度足夠讓輪椅經過，也設有斜台，方便傷健人士使用。



手術室大樓工地將會圍上帆布，以保障附近大樓及途人。



工程已推展至地面。

在興建臨時有蓋行人道之餘，我們也藉機豎立地盤圍板，並配上簡潔的設計和新大樓的模擬圖等，希望公眾對這個項目有更多認識。

注意衛生環境 杜絕鼠患蚊蟲

新手術室大樓工程正在全面施工，須使用到大量建築物料，並動用不同機器設備。因此，我們在醫院內特別撥出位置，讓承建商作暫時存放用途，惟存放雜物容易引起衛生問題。另一方面，新手術室大樓早前進行挖掘地庫部份，專家特別提醒要留意有可能引致昆蟲及老鼠出沒。



承建商存放建築物料的地方，須注意衛生問題。



針對上述情況，我們已經派員加強進行巡查，包括提醒承建商妥善放置建築物料，以及適時處理廢料，減少堆積，亦會加強滅鼠工作；但凡發現任何可能引起蟲患或鼠患的跡象，更會即時要求承建商跟進及改善。



承建商在當眼處張貼告示，提醒員工要注意環境衛生。

防蚊蟲措施及至工地附近

雖然近日天氣開始轉涼及乾燥，但我們仍然十分關注地盤積水問題，以免滋生蚊蟲。按照要求，承建商須定期在工地和附近範圍採取防蚊措施，包括噴灑滅蚊噴霧、放置蚊砂和蚊油等。我們亦繼續保持與食物環境衛生署的代表會面和檢視各項措施，務求全方位杜絕蚊蟲和鼠患。



工作人員在不同位置擺放老鼠藥。



直升機升降不受吊重機運作影響

我們在上一期的手術室大樓擴建計劃通訊中，報道工地已經豎立起吊重機。吊重機至今運作暢順，而吊重機也不影響政府飛行服務隊的直升機在屯門醫院順利升降。

鑑於屯門醫院設有直升機坪，確保政府飛行服務隊的直升機可以順利運送傷者至急症室搶救，是我們其中一項最關注題目，所以在設計及豎立吊重機的過程中，我們一直諮詢政府飛行服務隊的意見。



直升機停機坪位於工地對出的空地。



我們按照屋宇署的規定，應付強風吹襲期間的天秤安全。

成功抵禦強風

在吊重機豎立後，本港曾經懸掛三號熱帶氣旋警報。我們按照屋宇署的指引，啟動預先制訂好的程序，即為吊重機的天秤解鎖，以便天秤轉動，減少風阻。事後我們與承建商重新檢視整個處理程序，認為屬安全的做法；而此舉亦可為日後我們遇到更強的颱風時，作更好的準備。

另外，由於直升機升降會令地面的氣流驟變，我們也特別通知承建商一旦有直升機升降時，工地的工作人員須暫時離開指定範圍，以確保他們自身及直升機的安全。



Erection of Hoarding and Covered Walkway for Better Protection

The construction works of Tuen Mun Hospital Operating Theatre Block has already reached the ground level and more and more work-at-height activities will be taken in the near future. In order to enhance safety, hoarding and covered walkway were set up around the site boundaries in order to provide a safe pathway for pedestrians. The covered walkway with ramp is wide enough for wheelchair access.

Simple graphic pattern to illustrate the design concept of the Operating Theatre Block has been projected on the hoarding. Dust and sound screens will be installed in the next stage to provide additional protection, as well as to minimize the impact to existing hospital buildings.



Maintaining safety of tower crane

The tower crane is now in operation, for which we have already reported in our last newsletter. Several helicopter landings happened smoothly in the past few months. We will keep close communication with Government Flying Service and Hong Kong Fire Services Department on the arrangement. Meanwhile, the safety issue of tower crane in days of strong winds is also our concern. According to the recommendation made by Buildings Department, the tower crane must be unlocked to allow free lateral rotation under strong winds. This practice had been executed several times and demonstrated that the tower crane is running safely.

Enhancing pest and rodent control

Albeit it is already winter, we do pay great attention on pest and rodent control. The contractors are asked to store the materials (e.g. steels and timber) properly and remove the wastage in time. Other proactive and preventive measures, including fogging of insecticides at outdoor areas twice a week, application of larvicide oil and sand at water drainage, daily inspection to clear stagnate water and using poisonous bait or traps, are conducted regularly to maintain a good environmental hygiene standard.

如對擴建計劃有任何意見或查詢，歡迎透過以下途徑向我們反映。

Should you have any comment or advice about the project, please feel free to let us know.

電話 Tel : 2468 5464

傳真 Fax : 2464 4643

電郵 Email : ntwc.pa@ha.org.hk

優化設施 提升服務
Enhancing Facilities Improving Services